12th St. Brandywine Creek monitoring #2

June 2001 HARDNESS

U.S. EPA Region III Office of Analytical Services and Quality Assurance Fort Meade, Maryland



ANALYTICAL REPORT

12TH STREET LANDFILL
SUPERFUND REMOVAL/REMEDIAL
Lab Request # REQ01139

June 25, 2001



June 25, 2001

ANALYTICAL RESULTS: 12TH STREET LANDFILL [REQ01139]

Dear Michael Towle (3HS31),

Enclosed is our analytical report for the above case. It is organized into several sections: Analytical Request and Sample Descriptions, Organic, Inorganic, and Microbiological Results. All data were peer reviewed.

Analytical Request and Sample Descriptions: (General)

Each laboratory assigned number, station, description, matrix, sample date and locational data is reported. A table summarizes the tests assigned to each sample. A glossary and qualifier code definition is provided.

Inorganic Results:

For requests assigned inorganic tests, results are grouped by service group, e.g., Metals. Sample results are reported; non-detects are provided with the actual quantitation limit. Method description and quality control protocols are described in analyst narratives.

Organic Results:

For requests assigned organic tests, results are grouped by service group, e.g., Volatile Organic Compounds. Only detected analytes are reported. Nominal Quantitation Limit (NQL) tables are provided for each service group. Specific information for the calculation of Actual Quantitation Limits (AQL) achieved for a given sample is included. Quality control values are provided in summary tables with acceptance criteria. Method description and quality control protocols are described in analyst narratives.

Microbiological Results:

For requests assigned microbiological tests, sample results and quality control values are incorporated into a single table. Method description and quality control protocols are described in analyst narratives.

If you have any questions we may be reached at 410-305-2658.

Approval for Release:

Susan Warner

Site Contact(s): (b) (4) (TETRA TECH EM INC.)

Michael Towle (3HS31)

Section: GENERAL

Page: B1

Facility: 12TH STREET LANDFILL

Program: SUPERFUND REMOVAL/REMEDIAL

Lab Request #: REQ01139

SAMPLE DESCRIPTIONS

Sample # Station, Description Matrix Type Date Time Latitude Long	
	<u>jitude</u>
01061917 STA SW-1, SW-1(downstream bank sample) Water - Type Unspecified GRAB 06/18/01 10:45	
01061918 STA SW-2, SW-2(midstream bank sample) Water - Type Unspecified GRAB 06/18/01 10:55	
01061919 STA SW-3, SW-3(upstream bank sample) Water - Type Unspecified GRAB 06/18/01 11:05	
01061920 STA SW-4, SW-4 (middle of Brandywine Creek) Water - Type Unspecified GRAB 06/18/01 11:15	
01061921 STA SW-5, SW-5(field blank) Water - Type Unspecified GRAB 06/18/01 10:30	

Section: GENERAL

Page: C1

Facility: 12TH STREET LANDFILL

Program: SUPERFUND REMOVAL/REMEDIAL

Lab Request #: REQ01139

TESTS REQUESTED

Inorganic Test Assigned	San	ple	No.	0106	19-	14. 15	8.487	Kari S		S. 120	State of the	14 1 14 1 1
	17	18	19	20	21		784.A	18 17	77.8		* 1993	
Hardness	Х	Х	X	Х	X		<u></u>					

Section: General., Page: D1


QUALIFIER CODE AND GLOSSARY DEFINITIONS

Oug	lifier	Cod	00
CHIA	mmer	Lou	

<	=	Sample value is below the quantitation limit. Quantitation limit reported.
=</td <td>=</td> <td>Reported value is estimated. Sample was analyzed in duplicate, one value is equal to or above the quantitation limit and one below. Average of quantitation limit and detected value reported.</td>	=	Reported value is estimated. Sample was analyzed in duplicate, one value is equal to or above the quantitation limit and one below. Average of quantitation limit and detected value reported.
>	=	Sample value is above the quantitation range.
Α	=	Quality control value is outside acceptance limits.
В	=	Not detected substantially above (10 times) the level reported in the laboratory or field blanks (includes field, trip, rinsate, and equipment blanks).
С	=	See report narrative for analyst's observations concerning this result.
 D	=	Sample and duplicate values are below the quantitation limit. Quantitation limit reported.
E	=	Value exceeds a theoretically greater value (e.g. dissolved > total, orthophosphate > total phosphorus). However, the difference is within the expected precision of the analytical techniques and is not statistically significant.
I	=	An interference exists which masks true response. See report narrative for explanation.
J	=	Analyte present. Reported value is estimated; concentration is outside the range for accurate quantitation.
K	=	Analyte present. Reported value may be biased high. Actual value is expected to be lower.
L	=	Analyte present. Reported value may be biased low. Actual value is expected to be higher.
N	<u>-</u>	Presumptive evidence indicates the presence of the compound. Special methods and/or method modifications may be needed to confirm its presence or absence in future sampling efforts.
NA	=	Analysis was not requested.
Q	=	No analytical results. See report for explanation.
Ŕ	=	Unreliable results. Analyte may or may not be present in the sample. Supporting data is necessary to confirm results.
T .	=	Tentatively Identified Compound. Identified as a result of a library search using the EPA/NIH Mass Spectral Library. Authentic standards were not available to properly identify and quantitate the compound. The reported concentration is an estimate.
TD	=	Spike recovery too dilute for accurate quantitation.
ÜĴ	=	Not detected. Quantitation limit is estimated.
ÜL	=	Not detected. Quantitation limit is probably higher.

Glossary:

()	=	Numbers in parentheses are analytical spike recoveries (e.g. post-digestion spikes).
()	=	Numbers in brackets are matrix spike recoveries (e.g. pre-digestion spikes).
MS/MSD	=	Matrix spike/matrix spike duplicate; a known increment of target analyte made to a sample before preparation or analyses.
MSA	=	Method of Standard Additions
RPD	=	Relative Percent Difference; the results for duplicate analyses are presented as the mean and the relative percent difference.





INORGANIC ANALYTICAL REPORT

12TH STREET LANDFILL
SUPERFUND REMOVAL/REMEDIAL
Lab Request # REQ01139

U.S. EPA Region III

Office of Analytical Services

and Quality Assurance Fort Meade, Maryland

Facility: 12TH STREET LANDFILL

Program: SUPERFUND REMOVAL/REMEDIAL

Lab Request #: REQ01139

Section: INORGANIC

Page: A1

INORGANIC ANALYTICAL SAMPLE RESULTS

Sample Number:	01061917		0106191	8		0106191	9		0106192	0		
Station ID :	SW-1		SW-2			SW-3			SW-4			
ANALYTES	SAMPLE		SAMPLE			SAMPLE	W-L		SAMPLE			
Hardness	Units: mg/L % Rec	RPD	mg/L	% Rec	RPD	mg/L	% Rec	RPD	mg/L	% Rec	RPD	
Hardness	71.4	0	80.2	[100]		76.0			80.6		0	

Sample Number:

01061921

Station ID :

SW-5

ANALYTES

FIELD BLANK

Hardness

Units: mg/L % Rec RPD

Hardness

<3.3

OFFICIAL CONTRACTOR OF THE CON

Section: Inorganics

Page: 1

Hardness Determinations

Analyst:



Methods:

Samples from 12TH STREET LANDFILL (REQ01139) were prepared for analysis by acid digestion and analyzed by inductively coupled plasma optical emission spectrometry. Hardness is reported as the sum of calcium plus magnesium as calcium carbonate. The results are presented in the attached table. The following are the digestion and analytical techniques and methods employed:

<u>Digestion Methods</u> EPA Method 200.2 (1)

Analytical Methods

Method 200.7 and Internal SOP R3-QA132, elements by ICP-AES (1) Method 2340 B., Hardness by Calculation (2)

- (1) EPA Methods for the Determination of Metals in Environmental Samples, May 1994.
- (2) Standard Methods for the Examination of Water and Wastewater, 18th Edition, 1992.

USEPA Contract Laboratory Program Generic Chain of Custody

Refe	rence	e Case:	
Refe	rence	e Case:	

Client No:

SDG No:

R31032

Date Shipped: 6/18/2001 Carrier Name: FedEx

825081938924 Airbill:

Shipped to:

US EPA Region 3 OAS/QA **Environmental Science**

Cente

701 Mapes Road Fort Meade MD 20755-5350

Date Received/Received by:.... Unit Price: _ Lab Contract No:___

Date Received/Received By:___

Transfer To: _

Price: . Lab Contract No: ____

Sampler (Sign Received By: Date / Time: Relinquished By: Received By: Date / Time: Relinquished By: Received By: Date / Jime: Relinquished By:

SAMPLE No.	MATRIX/ SAMPLER	CONC/ TYPE	ANALYSIS/ TURNAROUND	TAG No./ PRESERVATIVE	STATION LOCATION	SAMPLE COLLECT DATE/TIME	SAMPLE No.	FOR LAB USE ONLY Sample Condition On Receipt
SW-1 (downstream	Surface Water/	M/G	HARD (14)	11 (HNO3) (1)	SW-1 (downstream bank sample)	6/18/2001 10:45 @1 Ø	619-17	
ban SW-2 (midstream	Surface Water/	M/G	HARD (14)	12 (HNO3) (1)	SW-2 (midstream bank sample)	6/18/2001 10:55 -/8		
bank SW-3 (upstream	Surface Water/	M/G	HARD (14)	13 (HNO3) (1)	SW-3 (upstream bank sample)	6/18/2001 11:05 - /9		
bank SW-4 (middle of	Surface Water/	M/G	HARD (14)	14 (HNO3) (1)	, <i>,</i>	6/18/2001 11:15 - 20		
Bran SW-5 (field blank)	(b) (4) Field (C)	_ M/G	HARD (14)	15 (HNO3) (1)	•	6/18/2001 10:30 - 2	1	

Shipment for Case Complete?Y	Sample(s) to be used for laboratory QC: SW-4 (middle of Bran	Additional Sampler Signature(s):	Cooler Temperature Upon Receipt:	Chain of Custody Seal Number:
Analysis Key:	Concentration: L = Low, M = Low/Medium, H = I	High Type/Designate: Composite = C, Grab =	= G	Custody Seal Intact? Shipment Iced
HARD = Hardness				

PR provides preliminary results. Requests for preliminary results will increase analytical costs.

Send Copy to: Contract Laboratory Analytical Services Support, 2000 Edmund Halley Dr., Reston, VA. 20191-3436 Phone 703/264-9348 Fax 703/264-9222

TR Number: 3-555513690-061801-0002

	Fedex USA Airbill	825081938924	0200 form	FedEx Retrieval Copy
	1 Fg/m Sender's FedEx Account Number	2551 4203 8	4a Express Package Service 1	Packages up to 150 lbs. Delivery command may be later in some areas. Vernight 6 Faflest next business morning delivery to select locations
1	Sender (b) (4) Name	Phone 610 485 6410	3 FedEx 2Day* Second business day 20 FedEx Express Sar	/CT* * FedEx Envelope/Letter Rate not available Minimum charge: One-pound rate
	Talo Tal For	Tal	4b Express Freight Service	Packages over 150 lbs. Delivery commitment may be later in some areas.
	company Tetre Tech Erri Address 709 Chelson Plan	<u> </u>	7 FedEx 1Day Freight* 8 FedEx 2Day Freight * Call for Confirmation:	nt 83 FedEx 3Day Freight Third business day
	City Bothwan	State PA ZIP 19066	5 Packaging 6 FedEx Envelope/ Letter* 2 FedEx Pak*	* Declared value limit \$500 1 X Other Pkg. Includes Fords Box, Fords Yube, and customer pkg.
	2 Your Internal Billing Reference 69031R	Ecoron.	6 Special Handling	Include FedEx address in Section 3.
	3 To Recipient's Pax Sosaski	Phone 410 305-2667	FedEx Priority Overnight FedEx Priority Overnight	HOLD Seaturday at FedEx Location State and Edition Available and Infect Princy Overright edit First Overright select locations
; 1	Company US EAR Region 3 CAS Address Environmental Severe	40		6 Dry Ice 9 UN 1845 xkg Cargo Aircraft Only
:	To "HOLO" at FedEx location, print FedEx address.	AAG CBUUDI ORMASI ID 1-10- DOYEZ OL 1-10- COCES.	7 Payment Bill to: Enter FedEx Acc. No. or Credit Co 1 Sender Acct. No. in Section 2 Recipient 3 Third Party will be bibled.	rd No. below. Obtain Recip. Acct No. 4 Credit Card 5 Cash/Check
	701 Mapes Road	Dept/Roor/Suite/Room	FedEx Acrt. No. 18 ZZ - 3Z9Z	Date
	city Fort Meade	State MD ZIP 20755-5350	Total Packages Total Weight	Total Charges
	8250 835	13 8924	10ur liability is limited to \$100 unless you declare a higher value. See th 8 Release Signature Sign to authorize delivery without obtain	ning signature
į			By signing you authorize us to deliver this shipment without is and agree to indemnify and hold us harmless from any result. Rev. Data 7/00-Part #154815+ 03 1994-72000 Fedt + PRINTED IN U.S. A.	ing claims.

DATE:

June 15, 2001

SUBJECT:

Scheduled Samples for 12TH STREET LANDFILL

EPA

FROM:

(b) (4)

Sample Manager

TO:

Michael Towle (3HS31)

DAS or NSF #: DAS R31032

The Office of Analytical Services and Quality Assurance (OASQA) will analyze samples from the 12TH STREET LANDFILL site. We are expecting to receive samples to arrive by June 20, 2001. If you ship the samples on time, barring any unforeseen difficulties, the fully validated analytical report will be sent to you within 28 calendar days.

We plan to analyze the following:

Parameter Matrix Description # of Samples
HARDNESS Water - Type Unspecified 5

If the parameters requested are incorrect, please call immediately.

Please have the sampler(s) sign as well as print his/her name on the chain of custody form(s). If you encounter a delay in shipping the samples, kindly notify me at (410)-305-2600 at least 24 hours before the samples are due to be shipped.

Comments:

OPTIONAL FORM 89 (7-90)	
FAX TRANSMIT	TAL # of pages > /
Michael Towle	Fro(b) (4)
USEPA - 3H531	Phone #10.305.2625
215.814.32.54	Fax #
NBN 7540_01_317_7368 S098_101	GENERAL SERVICES ADMINISTRATION

7 \$\mathbb{G}4103053093

U.S. EPA Region III Office of Analytical Services and Quality Assurance

and Quality Assurance Fort Meade, Maryland

Facility: 12TH STREET LANDFILL

Program: SUPERFUND REMOVAL/REMEDIAL

Lab Request #: REQ01139

Section: INORGANIC

Page: Al DRAFT

INORGANIC ANALYTICAL SAMPLE RESULTS

Sample Number: Station ID : ANALYTES	01061917	01061918	01061919	01061920
	SM-1	SN-2	SW-1	SW-4
	Sanpli	SAMPLE	SAMPLE	Sample
Hardness	Units: mg/L % Rec RPD	mg/L % Rec RPD 80.2 [136]	mg/L % Rec RPD 76.0	mg/L % Rec RPD 80.6 0

Sample Number: Station ID :

ANALYTES

esenbrak asentrak 01061921


Sti-5

FIBLD BLANK

United mg/L & Rec RPD

<3.2

DAS NO. R31032



OPTIONAL FORM 99 (7-50)